


Contoured Headrest Assembly

SECTION VI PARTS LIST



MA201220

Item	Part No.	Description	Qty.	Item	Part No.	Description	Qty.
	9A142001	Countoured Headrest Assembly (Includes Items 1 thru 21)	1	12	• 042-0002-08	• Dowel Pin	3
1	• 050-2570-10	• Pivot Bracket	1	13	• 051-0080-00	• Draw Bar	1
2	• 040-0250-104	• Screw	4	14	• 020-0115-02	• Handle Casting	1
3	• 040-0250-11	• Cap Screw	1	15	• 042-0014-04	• Shoulder Screw	2
4	• 040-0010-14	• Set Screw	1	16	• 045-0001-29	• Washer	6
5	• 057-0048-00	• Pivot Bar	1	17	• 050-3824-10	• Headrest Bracket	1
6	• 030-0743-10	• Headlock Weldment	1	18	• 040-0010-43	• Screw	4
7	• 040-0250-54	• Screw	8	19	• 045-0001-12	• Spring Washers	4
8	• 041-0250-12	• Jam Nut	1	20	• 041-0010-10	• Lock Nut	2
9	• 040-0250-70	• Set Screw	1	21	• 028-0277-00	• Contour Headrest	1
10	• 030-0123-12	• Head Pivot Handle Weldment	1	22		Back Casting (Refer to "Chair Frame Assembly" in Service Manual)	Ref
11	• 057-0048-01	• Pivot Bar	1				

Always Specify Model & Serial Number